

Michael O. Leavitt Governor Kathleen Clarke Executive Director Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

April 20, 2001

CERTIFIED RETURN RECEIPT 7000 0520 0021 7582 9002

Paula Doughty Kennecott Utah Copper 8315 West 3595 South Magna, Utah 84044-6001

Re: <u>Five-Year Review of Reclamation Surety Estimate, Kennecott Utah Copper, Pine Canyon\Carr Fork, M/045/004, Tooele County, Utah</u>

Dear Ms. Doughty:

The Division is performing the periodic review of reclamation surety estimates to verify their accuracy and make adjustments for escalation and any site modifications that could result in a change of the surety amount presently being held for the site. Division policy requires that surety estimates being held by the State include a five year escalation and be reviewed every five years. A number of these five-year reviews are overdue and were postponed due to higher permitting priorities.

The reclamation surety for Kennecott Utah Copper, Pine Canyon\Carr Fork Project was due for review as of 1997. To assist us in this review, we request an updated map of your site showing current surface facilities and disturbances. Please provide the updated map at a scale of not less than 1 inch = 500 feet, which includes: buildings, stationary mining/processing equipment, roads, utilities, power lines, drainage structures (i.e. berms, culverts, etc.), topsoil, ore and product storage areas, overburden/waste dumps, tailings or processed waste facilities, solid and liquid wastes, and wastewater discharge treatment and containment facilities, etc. This map should include all areas which have been affected by this operation to date. Please ignore items listed above which do not apply to your site.

If any reclamation has been completed on the site since the last surety estimate review, please provide a separate map of the same scale as the site map, clearly identifying these reclaimed areas, the acreage affected, and the date of the reclamation. Please cross-hatch or shade the areas

Page 2 Kennecott Utah Copper M/045/004 April 20, 2001

to identify the reclamation treatments (i.e. ripping, regrading, mulching, seeding, etc.) which have been applied.

Please provide this information within the next 60 days or no later than June 20, 2001. If you are unable to provide this information in this time frame, please contact the Division with justification for requesting additional time. Thank you for providing this information to assist us in our surety estimate review. If you have any questions concerning this letter, please contact Doug Jensen at (801) 538-5382.

Sincerely,

D. Wayne Hedberg Permit Supervisor

Minerals Regulatory Program

jb M45-04-bnd-rvw.doc